

10 617 693

OFC

PATENT Customer No. 22,852 Attorney Docket No. 08726.0018-00000

## IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re U.S. Patent No.: 6,915,656 B2	)	
Inventor: Frank W. RATLIFF	)	
Issue Date: July 12, 2005	)	Certificate AUG 1 7 2005
For: HEAT PUMP SYSTEM	)	
Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450		of Correction
Sir:		

## REQUEST FOR CERTIFICATE OF CORRECTION

Pursuant to 35 U.S.C. § 254, and 37 C.F.R. § 1.322, this is a request for a Certificate of Correction in the above-identified patent. The mistakes identified in the appended form are the fault of the U.S. Patent and Trademark Office, as clearly shown by the application which matured into this patent.

Two (2) copies of PTO Form 1050 are appended. The complete Certificate of Correction involves one (1) page.

While Applicants do not believe that any fees are due upon filing this Request, authorization is hereby given to charge any fees due in connection with the filing to Deposit Account No. 06-0916.

Issuance of the Certificate of Correction containing the corrections on the attached PTO Form 1050 is earnestly requested.

Respectfully submitted,

FINNEGAN, HENDERSON, FARABOW,

GARRETT & DUNNER, L.L.P.

Dated: August 12, 2005

Roland G. McAndrews

Reg. No. 41,450

## UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.:

6,915,656 B2

ISSUED:

A. A

July 12, 2005

**INVENTORS:** 

Frank W. RATLIFF

It is hereby certified that errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Claim 2, column 9, line 48, replace "superchargers" with --supercharger--;

Claim 3, column 9, line 50, replace "compressing" with --comprising--; and

Claim 20, column 11, line 6, replace "exchanger." with --exchangers--.

MAILING ADDRESS OF SENDER

Patent No. 6,915,656 B2

Finnegan, Henderson, Farabow, Garrett & Dunner, L.L.P. 901 New York Avenue, N.W. Washington, D.C. 20001-4413 No. of additional copies @ .30¢ per page